Split HeliRoll® Cluster Service Kit



Are there damaged or missing HeliRoll® Clusters on your Commander®?

Oshkosh AeroTech offers an economical, time-saving option when replacing these – our Split Service HeliRoll® Cluster Kit. Replacing damaged clusters on the convey system of a loader can be labor intensive. Our Split Service HeliRoll® Cluster Kit allows the technician to simply replace the cluster without having to disconnect convey chains or remove and disassemble the HeliRoll® shaft assembly. Three simple steps:

- 1) Remove two rollers on opposite sides of the HeliRoll cluster from one another.
- 2) Cut or chisel through the aluminum cluster casting at these two locations to remove.
- 3) Install the clamshell halves of the new Split Service HeliRoll® Cluster kit and assemble with a 10mm wrench or socket.





Oshkosh AeroTech part numbers:

624-4312-001 Left-hand Split Service HeliRoll® Cluster kit 624-4312-002 Right-hand Split Service HeliRoll® Cluster kit



Contact your parts representative to order!

ORLANDO

Tel+1.800.821.3019 Int'l +1.407.850.4208

LEKTRO

Tel +1.407.850.2899

LONDON

Tel +44.020.8831.2200

MADRID

Tel +34.91.877.5883

SINGAPORE

Tel +65.6542.9272

KUNSHAN

Tel +86.512.3663.0570



oshkoshaerotech.com An Oshkosh Corporation (NYSE:OSK) Business

